

Accident Investigation Ship Design Report 2008-02

Thursday, 03rd July 2008

Two years ago, a port worker was fallen into an unprotected opening. He received heavy injuries at his shoulder.

The Investigation on board was leading to a weak point in construction of the vessel.

1. The unprotected opening in 2006.

Where a fixed ladder gives access to a platform through an opening in the platform, the opening shall be protected.



2. The safeguarded opening in 2008.

There are possibilities!

Risk assessments should be performed before an accident occurs.



Impressum

Herausgeber Behörde für Gesundheit und Verbraucherschutz (BGV)

Amt für Arbeitsschutz,

Billstraße 80, 20539 Hamburg,

www.hamburg.de/arbeitsschutz

Arbeitsschutztelefon +49 40 428 37-2112, Fax +49 40 428 37-3100

arbeitsschutztelefon@bgv.hamburg.de

Bezug: Merkblätter können Sie kostenlos unter der o.a. Anschrift bestellen,

sowie unter Telefon +49 40 428 37-3134, Fax +49 40 427 94-8048

publicorder@bgv.hamburg.de, www.hamburg.de/arbeitsschutzpublikation

Das Amt für Arbeitsschutz ist Partner von KomNet-Arbeitsschutz, einer kostenlosen Expertenberatung: www.hamburg.de/komnet